00862.022154





IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of: KOJI FUKUNAGA Appl. No.: 09/816,458) : Examiner: J. Schneider	
) : Group Art Unit: 2182	
		Filed: March 26,2001
For: INFORMATION SIGNAL PROCESSING APPARATUS AND METHOD	·) :)	
U.S. Patent No.: 7,177,959 B2	·)	
Issued: February 13, 2007) November 16, 2007	
Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450	Certificate	

CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

NOV 2 3 2007 of Correction

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

11/21/2007 AWONDAF2 00000021 7177959 01 FC:1811 100.00 OP Patentee's undersigned attorney may be reached in our Costa Mesa,
California office by telephone at (714) 540-8700. All correspondence should continue to
be directed to our address given below.

Respectfully submitted,

Edward A. Kmett Attorney for Patentee Registration No.: 42,746

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 Facsimile: (212) 218-2200

FCHS WS 1468569v1

Î

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO. : 7,177,959 B2

DATED

: February 13, 2007

INVENTOR(S) :

Fukunaga

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COVER SHEET:

(57) Abstract, Line 6, "instructionis" should read -- instruction is --.

SHEET 7:

FIG. 7, under REGISTER NAME, "CLOCK_STOROBE_ARRIVED," should read -- CLOCK STROBE ARRIVED, --.

SHEET 30:

FIG. 30, "LIGTH" should read -- LIGHT --.

COLUMN 11:

Line 11, "relationship" should read -- relationships --.

COLUMN 16:

Line 34, "transferred)" should read -- transferred). --.

COLUMN 22:

Line 7, "have" should read -- has --.

FCHS_WS 1468557v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

PATENT NO. 7,177,959 B2

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82) 1468557v1(Form#30)

NOV 2 9 2007



Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

7,177,959 B2

DATED

February 13, 2007

INVENTOR(S) :

Fukunaga

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COVER SHEET:

(57) Abstract, Line 6, "instructionis" should read -- instruction is --.

SHEET 7:

FIG. 7, under REGISTER NAME, "CLOCK_STOROBE_ARRIVED," should read -- CLOCK_STROBE_ARRIVED, --.

SHEET 30:

FIG. 30, "LIGTH" should read -- LIGHT --.

COLUMN 11:

Line 11, "relationship" should read -- relationships --.

COLUMN 16:

Line 34, "transferred)" should read -- transferred). --.

COLUMN 22:

Line 7, "have" should read -- has --.

FCHS_WS 1468557v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. 7,177,959 B2

MOV 29 2007

No. of add'l. copies @ 30¢ per page



Form PTO 1050 (Rev. 3-82) 1468557v1(Form#30)